

Test Report No.: SZXEC23001876819 **Date:** Aug 24, 2023 Page 1 of 4

Client Name: DIOS TECH

Client Address: 3F, BUILDING A1-A2, FENGMINGGU INTELLIGENT INDUSTRIAL PARK, 4048 SONGBAI

ROAD, FENGHUANG STREET, GUANGMING NEW DISTRICT, SHENZHEN, CHINA

Sample Name: Semiconductor Component

Model No.: TO-252

Client Ref. Information: SOD123FL SMA SMB SMC MBS MBF ABS ABF DBS UMC UMSB

MSB DO-27 DO-41 TO-252 TO-251 TO-263 TO-220 TO-220F TO-247

TO-3P TO-264 TO-3P TO-264 KBP GBJ GBU DIP-4 SOP-4

The above sample(s) and information were provided by the client.

SGS Job No.: SZP23-012963 Sample Receiving Date: Aug 11, 2023

Testing Period: Aug 11, 2023 ~ Aug 17, 2023

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).
Test Result(s): Please refer to next page(s).

Test Requirement	Conclusion
Halogen	See Results

Signed for and on behalf of

SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch



Approved Signatory

Ford





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-p-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (85-755) 8307 1443.

Room 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 3 & Room 101-901, Plant 3, Room 301-901, Plant 3, Room 301-901, Plant 3, Room 301-901, Plant 3, Room 301-901, Plant 3, Room 301-901 Plant



Test Report No.: SZXEC23001876819 Date: Aug 24, 2023 Page 2 of 4

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description	
SN1	A5	SZX23-0018768-0001.C005	"Semiconductor Component"(mixed)	

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A5
Fluorine(F)	mg/kg	20	ND
Chlorine(CI)	mg/kg	50	ND
Bromine(Br)	mg/kg	50	84
Iodine(I)	mg/kg	50	ND

Remark1: The sample(s) was/were analyzed on behalf of the applicant as mixing sample in one testing. The above result(s) was/were only given as the informality value and only for reference.

Remark2: Results & photo(s) of this report refer to test report SZXEC23001876809.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.




Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-en-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755) 8307 1443,



Test Report ATTACHMENTS

Halogen Testing Flow Chart





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@gs.com.

Acceptable 16 CM-Doccheck @sgs.com 5/1, Plant 3 Room 101, Plant



Test Report No.: SZXEC23001876819 Date: Aug 24, 2023 Page 4 of 4

Sample Photo:



SGS authenticate the photo on original report only

*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.sapx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.sapx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgety or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@gs.com"

Roum 101-901, Plant 44 Room 101, Plant 24 Room 101, Plant 24 Room 101, Plant 24 Room 101, Plant 34 Room 101-901, Plant 34 Room 101, Plant 34 Room 101, Plant 34 Room 101, Plant 34 Room 101, Plant 34 Room 101-901, 28101, 38101 501 邮第:518129 www.sgsgroup.com.cn
中国 - 广东 - 深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田) 工业厂区厂房4号101-901, 28101, 38301-501 邮第:518129 t(86-755) 25328888 sgs.china@sgs.com